

## Auricon 4.4 Driver Update

This update fixes a bug with the monitor faders when the card is configured for one of the lower output levels, as well as introducing some changes to bring it into line with other products in the range.

- The monitor fader gain setting is now correct at all output level configurations.
- The maximum input and output gain is now 0dB instead of the previous +6dB which was causing some confusion and incorrect operation with some software.
- The input/output level setting on the configuration page is now expressed in terms of the peak programme level rather than line-up level. The mapping is +8dBm -> +24dBu, +4dBm -> +20dBu and 0dBm -> +16dBu.
- Additional peak programme levels of +15dBu, +18dBu and +22dBu have been included in the options.

Note that, because of the changes to the fader maximum levels, all faders will be set to their default levels when the driver update is applied (wave inputs and outputs to 0dB and the monitor faders to off).